SUNSHINE PRECIOUS METALS INCORPORATED

A Wholly-Owned Subsidiary of





SUNSHINE MINING COMPANY

15988 Silver Pass Road P.O. Box 250 Eureka, Utah 84628 (801) 433-6854 Fax (801) 433-6639

January 17, 1991

D. Wayne Hedberg
Permit Supervisor
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Dear Mr. Hedberg:

Please find enclosed the "Annual Report Of Mining Operations" for the 1990 reporting year.

This report is for:

Mine No. Mine Name

M/049/009 Apex/Burgin/Trixie Mine

If you have any questions or require any additional information regarding this annual report please feel free to contact me.

Very truly yours,

Glenn Mellor Senior Geologist

GM: 1r1

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1.	Report Time Period: From (mo./yr.) Jan. 1990 To (mo./yr.) Dec. 1990				
2.	DOGM File Number (original notice): M / 049 / 009				
3.	Mine Name: Apex/ Burgin/ Trixie				
4.	Legal Description (Location of Lands Affected):				
	SE 1/4, SE 1/4, Section 15, Township 10S, Range 2W				
	SE 1/4, NW 1/4, Section 22, Township 10S, Range 2W				
	<u>NW</u> 1/4, <u>NW</u> 1/4, Section <u>28</u> , Township <u>10S</u> , Range <u>2W</u>				
5.	Mineral(s) Mined: See ATTACHMENT A				
6.	Name of Operator or Company:Sunshine Mining company				
7.	Permanent Address: P.O. Box 250				
	Eureka, Utah 84628				

8.	Company Representative (or designated operator):					
		Name:	Glenn Mellor			
	•	Title:	Senior Geologist			
		Address:	P.O. Box 250			
		Phone:	Eureka, Utah 84628			
	Please check if any of the above information has changed since previous year.					
II.	MININ	g and re	ECLAMATION			
1.	Was the mine active during the past year? Yes ☐ No ☐ See ATTACHMENT B					
2.	If active, how much ore or mineral was mined?					
•	See ATTACHMENT B					
3.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.					
	See ATTACHMENT C					
		A-1-1-1-1				
						
4.	Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results. No major reclamation was undertaken during the past year.					
	 					
5.	What v	vas the to	tal unreclaimed acreage at years end?72.40			

6.	Briefly summarize mining and reclamation planned for the upcoming year. There is currently no major reclamation plan planned for				
	1991.	or recramation prain prainted for			
NOTE:	Section III., "Additional Information	on" applies only to <u>large mining operations</u> .			
III. <u>ADDITIO</u>	NAL INFORMATION				
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.				
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.				
IV. <u>SIGNATU</u>	JRE REQUIREMENT				
I hereby certify that the foregoing is true and correct.					
	Name (Typed or Print):	Glenn Mellor			
	Title of Operator:	Senior Geologist			
	Signature of Operator:				
	Date: January 17, 1991				
jb MNMR-AR					

SUNSHINE PRECIOUS METALS INCORPORATED

A Wholly-Owned Subsidiary of



SUNSHINE MINING COMPANY

15988 Silver Pass Road P.O. Box 250 Eureka, Utah 84628 (801) 433-6854 Fax (801) 433-6639

January 17, 1991

ATTACHMENT A:

5) Mineral(s) Mined

Trixie Mine - Gold- Silver-Copper Apex - Exploration Only Burgin - Inactive

ATTACHMENT B:

1) Was the mine active during the past year?

Trixie - Yes Apex - Exploration Only Burgin - Inactive

2) If active, how much ore was mined?

Trixie 31,115 Tons

ATTACHMENT C:

3) New or additional surface disturbances for the past year?

Trixie .344 Acres Apex .052 Acres Burgin -0- Acres

TOTAL: 0.396 Acres

Total reported acres 1989 - 72.00 Total reported acres 1990 - 0.40

Total Acres 72.40

New disturbances are the result of mine waste rock dump expansion. To minimize this impact we use broken waste rock as backfill into open stopes, when possible.